Licence No. : **SLA 28863**
Valid Upto : **16.7.2023**

Sandeep Kumar

Automobile Engineer,
Surveyor and Loss Assessor

873-B, Prem Nagar,
Yamuna Nagar – 135 001
Phone : 01732 – 231112
Mobile : 98960 – 95251
sandeepairi09@gmail.com
PAN No. : ACTPA1862F

PRIVATE & CONFIDENTIAL
MOTOR (INTERIM) SURVEY REPORT

Ref. No. 136/OIC/21/MTR **Dated : 12.02.2022.**

This report is issued by me as a licensed surveyor without prejudice, in respect of cause, nature and extent of Loss / Damage and is subject to terms and conditions of the insurance policy.			
⇨	Cover Note / Certificate of Insur. Co.	:	261701/31/2022/1292.
⇨	Policy No.	:	261701/31/2022/1292.
⇨	Period of Cover	:	20.06.2021 to 19.06.2022.
⇨	Date of Loss / Accident	:	07.02.2022.
⇨	IDV of the Vehicle	:	Rs. 70,000/-
⇨	Insurance Company's Claim No.	:	260011/31/2022/00031457.

	INSURANCE PARTICULARS		
⇨	Policy Issuing Office and Address	:	**The Oriental Insurance Company Ltd., BO Jagadhri Through Claim Hub, Ambala.**
⇨	Name of Insured	:	**Sh. Rakesh Kumar S/o Sh. Gian Chand, R/o Vill. Jain Mandir, Sadhaura, Distt. Yamuna Nagar.**
⇨	Financiers / Hypothecation if any	:	None.

	VEHICLE PARTICULARS		**RC Checked,Verified & found in order.**	
⇨	Regd. No. / Temp. Regd. No.	:	**HR71-A-4767.**	
⇨	Regd. Owner	:	**Sh. Rakesh Kumar S/o Sh. Gian Chand.**	
⇨	Make / Model	:	Maruti / Alto LX.	
⇨	Year of Manufacturing	:	2010.	
⇨	Date of registration	:	05.04.2011.	
⇨	Registration of valid upto	:	23.04.2025.	
⇨	Chassis No.	:	MA3EAA61S01614067	Physically Verified
⇨	Engine No.	:	F8DN4370249	Physically Verified
⇨	Class of Vehicle	:	LMV (CAR).	
⇨	Type of Body	:	Saloon.	
⇨	Registered Laden Weight/GVW	:	Kgs.	
⇨	Unladen Weight	:	1140 Kgs.	
⇨	Cubic Capacity	:	796 CC.	
⇨	No. of Persons Permitted as per RC	:	5.	
⇨	Permit No., Valid upto and Area	:	N.A.	
⇨	Authorization No. Valid upto and Area	:	N.A.	
⇨	Area of Operation / Route	:	N.A.	
⇨	Fitness Certificate valid upto	:	23.04.2025.	
⇨	Road Tax paid up to	:	One Time Tax Paid.	
⇨	Odometer Reading	:	139099 Kms.	
⇨	Fuel Used – Diesel / Petrol / CNG / LPG / Battery / Dual System	:	Petrol.	
⇨	Whether insured has insurable interest	:	Yes.	
⇨	Colour	:	S White.	

Licence No. : **SLA 28863**
Valid Upto : **16.7.2023**

Sandeep Kumar

Automobile Engineer,
Surveyor and Loss Assessor

873-B, Prem Nagar,
Yamuna Nagar – 135 001
Phone : 01732 – 231112
Mobile : 98960 – 95251
sandeepairi09@gmail.com
PAN No. : ACTPA1862F

	DRIVER PARTICULARS		**DL Checked,Verified & found in order.**
⇨	Name of Driver	:	**Sh. Rakesh Kumar S/o Sh. Gian Chand.**
⇨	Date of Birth	:	12.12.1962.
⇨	Driving License No.	:	HR-7120090045127.
⇨	Date of Issue & Validity	:	27.07.2009 Valid Upto 24.07.2026.
⇨	Licence Issuing Authority	:	SDM Bilaspur.
⇨	Authorized to Drive	:	For LMV & MCWG Only.
⇨	Badge No.	:	NA.
⇨	Special Endorsement on Licence if any	:	No.
⇨	Natuer of Goods carried	:	NO.
⇨	Weight of goods carried	:	NO.

	OTHER DETAILS			
⇨	Loan / Challan / Trip Sheet Details	Origin & Destination	:	NA.
		LR/Invoice No. & Date	:	NA.
		Transporter's Name	:	NA.
⇨	Passenger Details	Number of passengers carried	:	NA.
⇨		Occupants and details	:	Minor Injuries to Insured and his Son Sejal.
⇨	Accident Particulars	Date & Time of accident	:	07.02.2022 at about 07:00 P.M.
⇨		Place of accident	:	Vill. Bhagwali.
⇨		Survey Allotment Date	:	09.02.2022.
⇨		Survey conducted on and place	:	09.02.2022 at 02:00 P.M., at M/s Shree Ganesh Motors, Sadhaura.
⇨		Spot Survey done by	:	Spot Survey was not conducted.
⇨		Cause of accident as stated in claim form or by insured / representative	:	Insured was going to Sadhaura from Panchkula in his car, on the way, when he reached near site of accident, suddenly a cow came in front of car and car hit with cow from front and got unbalance and went below the road and overturned and thus the subject car got damaged.
⇨	Fatality / Injury Details	Details of TP Vehicle	:	NO.
⇨		Death / Injury details of insured vehicle	:	NO.
⇨		Death / Injury details of TP Vehicle	:	NO.
⇨		Third Party property damage	:	NO.
⇨	Police Report Details	Name of the police station	:	NO.
⇨		FIR No. and Date & Secton GD and 100 No. Dial	:	NO.
⇨	Other details and remarks	Whether documents verified, if so what are they (put a tick)		RC: YES; FC: YES; Permit: YES; Tax: YES; DL: YES; Challan / Trip Sheet: NA; Others: NO
⇨		Serial Numbers of Major parts and assemblies damaged.	:	
⇨		Verification of these	:	NA.

Licence No. : **SLA 28863**
Valid Upto : **16.7.2023**

Sandeep Kumar

Automobile Engineer,
Surveyor and Loss Assessor

873-B, Prem Nagar,
Yamuna Nagar – 135 001
Phone : 01732 – 231112
Mobile : 98960 – 95251
sandeepairi09@gmail.com
PAN No. : ACTPA1862F

		serial numbers with those mentioned in spot survey and deviation if any		
⇨		Whether MVI inspection done	:	NA.
⇨		Umber of photographs enclosed	:	20 Nos.
⇨		Whether towing done	:	NO.
⇨		Assessment done in accordance with Add-On cover, if any	:	NO, Add-On Cover.
⇨		Any deviation from the spot survey report	:	NA.
⇨		Comment on status of garage and workshop (authorized / local)	:	Local Repairer / Good Working.
⇨		Confirm that damaged noted in pre-acceptance inspecton report have been disallowed	:	Yes.
⇨		Any breach of policy terms and conditions and endorsement	:	NO.
⇨		Remarks on re-inspecton, where re-inspection is done by the same surveyor	:	NO.
⇨	Damages inspected (Technical description of damage)	List of parts	:	
⇨	Old damages notices	List of parts	:	NO.
⇨	Damages to be excluded due to electrical / mechanical failure	List of parts	:	NO.

⇨ **Assessment of Loss**

Details of Assessment of Parts :

Sr. No	Parts	Estimated	Assessed		
			Metal	Rubber	Glass
1.	Fan Assy. Eng. Cooling	3175.00	3175.00	0.00	0.00
2.	Radiator Assy.	2520.00	2520.00	0.00	0.00
3.	Unit Head Lamp RH	2150.00	0.00	2150.00	0.00
4.	Unit Head Lamp LH	2150.00	0.00	2150.00	0.00
5.	Switch Assy. Combination	1400.00	0.00	0.00	0.00
6.	Motor & Pump Assy. Wind Shield	258.00	0.00	258.00	0.00
7.	Tank Assy. Washer FR	200.00	0.00	200.00	0.00
8.	Strut Assy. Front Suspn. RH	1590.00	1590.00	0.00	0.00
9.	Strut Assy. Front Suspn. LH	1590.00	1590.00	0.00	0.00
10.	Mount Strut	70.00	0.00	0.00	0.00
11.	Bar Comp. Front Stabilizer	1655.00	1655.00	0.00	0.00

Licence No. : **SLA 28863**
Valid Upto : **16.7.2023**

Sandeep Kumar

Automobile Engineer,
Surveyor and Loss Assessor

873-B, Prem Nagar,
Yamuna Nagar – 135 001
Phone : 01732 – 231112
Mobile : 98960 – 95251
sandeepairi09@gmail.com
PAN No. : ACTPA1862F

12.	Tyre	5490.00	0.00	0.00	0.00
13.	Wheel Comp. Front	2500.00	1250.00	0.00	0.00
14.	Shaft Assy. Front Drive RH	4354.00	0.00	0.00	0.00
15.	Shaft Assy. Front Drive LH	4354.00	4354.00	0.00	0.00
16.	Knuckle Steering RH	1380.00	0.00	0.00	0.00
17.	Knuckle Steering LH	1380.00	0.00	0.00	0.00
18.	Arm Assy. Front Suspn.	1130.00	1130.00	0.00	0.00
19.	Steering Wheel	1120.00	0.00	0.00	0.00
20.	Pad Steering Wheel	156.00	0.00	0.00	0.00
21.	Column Assy. Collapsble Steering	2335.00	0.00	0.00	0.00
22.	Lower Shaft	1130.00	0.00	0.00	0.00
23.	Cover Assy. Steering Column	125.00	0.00	0.00	0.00
24.	Box Assy. Steering Gear	3400.00	3400.00	0.00	0.00
25.	Panel Comp. Front Hood	3009.00	3009.00	0.00	0.00
26.	Panel Front Fender RH	1420.00	0.00	0.00	0.00
27.	Panel Front Fender LH	1420.00	1420.00	0.00	0.00
28.	Panel Comp. Fender Apron RH	4200.00	4200.00	0.00	0.00
29.	Panel Comp. Fender Apron LH	4275.00	4275.00	0.00	0.00
30.	Panel Assy. Front End	2653.00	2653.00	0.00	0.00
31.	Extension Apron Upper RH	411.00	411.00	0.00	0.00
32.	Extension Apron Upper LH	411.00	411.00	0.00	0.00
33.	Member Comp. Apron Side RH	2640.00	0.00	0.00	0.00
34.	Member Comp. Apron Side LH	2730.00	2730.00	0.00	0.00
35.	Crossmember Comp. Dash Lower	2230.00	0.00	0.00	0.00
36.	Panel Comp. Side Body RH	6501.80	6501.80	0.00	0.00
37.	Panel Roof	3365.00	0.00	0.00	0.00
38.	Frame Roof Inner Front	325.00	325.00	0.00	0.00
39.	Frame Roof Inner Rear	181.00	0.00	0.00	0.00
40.	Panel Assy. Front Door RH	6065.00	0.00	0.00	0.00
41.	Panel Assy. Rear Door RH	6955.00	6955.00	0.00	0.00
42.	Front Bumper	2065.00	0.00	2065.00	0.00
43.	Panel Heat Insulator	360.00	0.00	0.00	0.00
44.	Cover Front Bumper	146.00	0.00	146.00	0.00
45.	Grille Front Bumper	545.00	0.00	545.00	0.00
46.	Stay Front Bumper	170.00	0.00	170.00	0.00
47.	Rear Bumper	2214.21	0.00	0.00	0.00
48.	Garnish Cowl Top	555.00	0.00	555.00	0.00
49.	Bracket Comp. Stabilizer RH	205.00	205.00	0.00	0.00
50.	Bracket Comp. Stabilizer LH	275.00	275.00	0.00	0.00
51.	Tray Comp. Battery	150.00	0.00	0.00	0.00
52.	Panel Instrument Main	2244.00	0.00	0.00	0.00
53.	Member Comp. Steering Support	1149.00	0.00	0.00	0.00
54.	Panel I/P Cluster	225.00	0.00	0.00	0.00
55.	Latch Hood	330.00	330.00	0.00	0.00
56.	Cable Hood Latch Release	124.79	124.79	0.00	0.00
57.	Glass Wind Shield	3835.00	0.00	0.00	3835.00
58.	Molding Wind Shield	370.00	0.00	370.00	0.00
59.	Condenser Assy.	4366.00	4366.00	0.00	0.00
60.	Sealent Set	1450.00	0.00	1450.00	0.00

Licence No. : **SLA 28863**
Valid Upto : **16.7.2023**

Sandeep Kumar

Automobile Engineer,
Surveyor and Loss Assessor

873-B, Prem Nagar,
Yamuna Nagar – 135 001
Phone : 01732 – 231112
Mobile : 98960 – 95251
sandeepairi09@gmail.com
PAN No. : ACTPA1862F

61.	Wiper Kit	455.00	0.00	455.00	0.00
62.	Air Drying Sealer	810.00	0.00	810.00	0.00
	Total	**116447.80**	**58855.59**	**11324.00**	**3835.00**
	Less Dep. 50%		**29427.79**	**5662.00**	**0.00**
	Total		**29427.80**	**5662.00**	**3835.00**

G.Total =Rs.29427.80+Rs.5662+Rs.3835 = Rs. 38925/-
Parts Allowed as per Dealer's List Price.

Details of Assessment of Labour :

Sr. No.	Labour			Claimed	Assessed
1.	Painting Charges			29160.00	16150.00
	RH Fender Painting	Rs.	1300.00		
	RH Front Door Painting	Rs.	1700.00		
	RH Rear Door Painting	Rs.	1700.00		
	RH Side Body Painting	Rs.	1600.00		
	Dicky Painting	Rs.	1600.00		
	Hood Painting	Rs.	1750.00		
	LH Fender Painting	Rs.	1300.00		
	Roof Painting	Rs.	2600.00		
	RH Apron Painting	Rs.	1000.00		
	LH Apron Painting	Rs.	1000.00		
	Front End Painting	Rs.	600.00		
	Total	**Rs.**	**16150.00**		
2.	Denting Charges			15000.00	7150.00
	RH Fender Denting	Rs.	250.00		
	RH Front Door Denting	Rs.	400.00		
	RH Rear Door Replacement	Rs.	300.00		
	RH Side Body Cutt & Welding	Rs.	600.00		
	Rh Susppn, Replacement	Rs.	300.00		
	Dicky Denting	Rs.	250.00		
	Hood Replacement	Rs.	200.00		
	LH Fender Replacement	Rs.	150.00		
	Roof Denting	Rs.	600.00		
	Front Bumper Replacement	Rs.	200.00		
	W/S Glass Replacement	Rs.	700.00		
	Engine Up & Down	Rs.	1000.00		
	AC Gas Charges(Less 50% of 1200)	Rs.	600.00		
	RH Apron Cutting & Welding	Rs.	600.00		
	LH Apron Cutting & Welding	Rs.	600.00		
	Front End Cutting & Welding	Rs.	400.00		
	Total	**Rs.**	**7150.00**		
			Total	**44160.00**	**23300.00**
	Less Dep. 50% on 25% of Paint Material Cost i.e. Rs. 4037.50 of Rs. 16150.00			**0.00**	**2018.75**
			Total	**44160.00**	**21281.25**
			Add CGST @ 9%	**3974.40**	**1915.31**
			Add SGST @ 9%	**3974.40**	**1915.31**
			Total	**52108.80**	**25111.87**

Licence No. : **SLA 28863**
Valid Upto : **16.7.2023**

Sandeep Kumar

Automobile Engineer,
Surveyor and Loss Assessor

873-B, Prem Nagar,
Yamuna Nagar – 135 001
Phone : 01732 – 231112
Mobile : 98960 – 95251
sandeepairi09@gmail.com
PAN No. : ACTPA1862F

SUMMARY OF ASSESSMENT

⇨	**New Parts**	**Rs.**	**38925.00**
⇨	**Labour Assessed**	**Rs.**	**25112.00**
⇨	**Total**	**Rs.**	**64037.00**
⇨	**Less Policy Clause**	**Rs.**	**1000.00**
⇨	**Total**	**Rs.**	**63037.00**
⇨	**Add Towing Charges**	**Rs.**	**1500.00**
⇨	**Total**	**Rs.**	**64537.00**
⇨	**Less Salvage Value**	**Rs.**	**3200.00**
⇨	**Net Loss Assessed**	**Rs.**	**61337.00**

Hence Net Loss Assessedy under this claim is Rs. 61337/- subject to your approval & policy conditions.

⇨	Documents verified if any		YES, RC & DL checked & verified.
⇨	Confirmation of Salvage Value and Crushing of Salvage		YES.
⇨	DYC from insured for assessed loss more than Rs. 1.00 Lac		NO.
⇨	Recommendations of any loss control measures		YES.
⇨	Close proximity		NO.

Any other comments:-

CASHLESS FACILITY NOT ALLOWED. PAYMENT TO BE MADE TO THE INSURED.
REPAIR ASSESSMENT EXCEEDS 75% OF IDV

Issued without bias and prejudice.

Enclosures		
Photographs	20	
Copy of Estimate,RC,DL,Ins.		
Claimform.		
S.V.		
S. Fee Bill.		
Online Verification of RC & DL.		

Yours faithfully,

(SANDEEP KUMAR)

Licence No. : **SLA 28863**
Valid Upto : **16.7.2023**

Sandeep Kumar

Automobile Engineer,
Surveyor and Loss Assessor

873-B, Prem Nagar,
Yamuna Nagar – 135 001
Phone : 01732 – 231112
Mobile : 98960 – 95251
sandeepairi09@gmail.com
PAN No. : ACTPA1862F